

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

558
WSW
1/2-1
0.849 mi.
4483 ft.

SURFSIDE -NYCHA
2926 WEST 27TH STREET
BROOKLYN, NY

NY LTANKS **U000410718**
N/A

Relative:
Higher

Actual:
3 ft.

LTANKS:

Name: SURFSIDE -NYCHA
Address: 2926 WEST 27TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9011481 / 2008-09-23
Facility ID: 9011481
Site ID: 185656
Spill Date: 1991-01-31
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: jkkann
Referred To: Not reported
Reported to Dept: 1991-01-31
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1991-02-08
Spill Record Last Update: 2008-09-23
Spiller Name: Not reported
Spiller Company: NYCHA
Spiller Address: 250 BROADWAY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 155282
DEC Memo:

"01/24/06: This spill transferred from J.Kolleeny to S.Kraszewski.
One TTF in 1990 for a 35K tank installed in 1974. Tank was repaired
and retested in 1993 and passed. Next test was in 1998. PBS database
shows tank as active. However, NYCHA Tank Status Report does not have
the tank listed for Surfside Houses. Unsure if tank is still active.
Also, since a spill was recorded for this site a subsurface
investigation must be performed to determine the extent of the
contamination. - SK 03/14/06: This spill reassigned to K.Tang. - SK
09/23/08: Documents related to tank tightness testing submitted to
the Department. Results indicate that manway gasket nuts and bolts
were cause of testing failure, they were replaced and the tank passed
testing. Spill closed based on this information. J.kann "
Remarks: "35K TANK FAILED HORNER EZY CHECK,SYSTEM TEST,GROSS LEAK,WILL
EXCAVATE,ISOLATE & RETEST."

All TTF:

Facility ID: 9011481
Spill Number: 9011481
Spill Tank Test: 1538203

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 185656
Tank Number: 001
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 185656
Operable Unit ID: 948499
Operable Unit: 01
Material ID: 428024
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported